

REGIONAL OFFICE, MYSORE-1
LAKE/TANK WATER SAMPLES RESULTS FOR THE YEAR 2013-14 (APRIL - 2013 to FEBRUARY - 2014).

Sl. No.	Name of the Lake/Tank	Sampling Station	May-13	Aug-13	Sep-13	Feb-14
1	Shettekere Lake	Upstream of the lake towards north western side	C	-	-	-
		Upstream of the lake towards western side	C	-	-	-
		Upstream of the lake towards south western side	C	-	-	-
		Downstream of the lake towards eastern side	E	C	-	D
2	Dalvai Lake	Sewage Joining point	E	E	-	E
		Upstream of the lake south western side	E	E	-	E
		Upstream of the lake towards south eastern side	E	E	-	E
		Downstream of the lake towards eastern side	E	E	-	E
3	Hebbal Lake	Upstream of the lake towards southwestern side	E	E	-	E
		Upstream of the lake towards eastern side	E	E	-	E
		Downstream of the lake towards northeastern side	E	E	-	E
		Downstream of the lake towards north western side	E	E	-	E
4	Dadadhalli Lake	Sewage Joining point	E	-	E	E
		Upstream of the lake towards eastern side	E	-	E	D
		Upstream of the lake towards southern side	E	-	C	D
		Downstream of the lake towards southeastern side	E	-	E	C
5	Kukkarahalli Lake	Upstream of the lake towards north western side	E	-	D	D
		Upstream of the lake towards northeastern side	E	-	D	D
		Upstream of the lake towards western side	E	-	D	D
		Downstream of the lake towards south eastern side	E	-	D	D
6	Karanji Lake	Upstream of the lake towards eastern side of sewage entr	D	-	D	E
		Upstream of the lake towards north eastern side	E	-	C	D
		Downstream of the lake towards southwestern side	D	-	C	D
		Water sample from Lake Centre point	E	-	C	D
		Downstream of the lake towards western side	C	-	C	D
7	Lingambudi Lake	Upstream of the lake towards Eastern side	E	-	E	E
		Upstream of the lake towards southwestern side	-	-	-	E
		Downstream of the lake towards southeastern side	-	-	-	E

